

April 1, 2019

Attn: Donald Serotta  
Town of Chester  
1786 Kings Hwy  
Chester, NY 10918

RE: 215 Black Meadow Road, Solar Project

Dear Donald,

The fence installed at the above reference solar site did not have the black vinyl coated chain link material. Conti Solar was unaware that the reason for the vinyl coating was at the request from the town, therefore the standard solar array galvanized fencing was installed. It was not noticed that only the fence fabric was to be vinyl coated, while all other components were to be galvanized. However, the fence was installed as a typical solar array fence, as the galvanized coating helps ensure the long life of the fence. The vinyl coating may crack and peel over time from the sun and weather and would not likely endure for the long life of the project. Also, as in a letter from the town landscape architect the galvanized fence material blends in the array racking material, and forms less of a visual obstruction. Galvanized fencing material is typically more suitable in an industrial setting and this fence conforms with the surrounding properties.

Very truly yours,



Jason Guertin  
Project Manager

Cc: