

Consulting Engineers

Alfred A. Fusco, Jr., P.E., Principal

Alfred A. Fusco, III, General Manager

- 233 East Main Street
 Middletown, NY 10940
 Phone: (845) 344-5863
 Fax: (845) 956-5865
- 19 Waywayup Lane
 Port Jervis, NY 12771
 Phone: (845) 956-5866

November 30, 2021

Donald Serotta, Planning Board Chairman Town of Chester 1786 Kings Highway Chester, NY, 10918

Re:

Oak Woods Subdivision Our File No. CH-186

Dear Chairman Serotta,

We have reviewed the submittal and offer the following:

PROJECT:

6 Lot Subdivision

SBL:

15-1-27.41

Acres:

26.9 Acres

Zone:

AR-3

Material Reviewed:

Revised subdivision plan 11/10/21 and response letter 11/16/21

Comments:

- 1. The updated sketch yield plan seems to comply with previous concerns. We do, however, need an area of disturbance for the two (2) wetland crossings; just for the record, it appears under the requirements.
- 2. Although a full SWPPP is not required, the Engineer needs to demonstrate that storm water peak flow rates from this development do not exceed pre-development levels. Possibly rain gardens or bioretention swales recommended.
- 3. There are symbols shown on the plan view and not shown in the legend. Please clarify.
- 4. Plans need to show soil stockpile locations for each lot. Also, stone check dams are required for driveways to help minimize soil erosion. Silt pond and/or traps are required at the base of construction of each home and should be sized appropriately.
- 5. Provide SHPO review letter.
- 6. Side slopes exceeding 3 on 1 require special slope protection. See lot 6 driveway grades and check all other locations.
- 7. Provide culvert sizes, inverts and slopes. Also, provide calculation to verify the pipe sizes necessary.

- 8. Provide driveway profiles due to the steep slopes.
- 9. Board comments.

Please advise if you have any questions.

Very truly yours,

Alfred A. Fusco Jr., P.E.

Fusco Engineering

& Land Surveying, P.C.

AAF/cam